

Important Pre-Installation Checks for the Maintenance Cartridge

HP Latex 800, 700, 630, R530 Printer series


Due to abnormal vibrations during transportation or incorrect handling during the out-of-the-box procedure, some parts in the maintenance cartridge may be displaced, creating a damage risk for the printer's internal components during installation or later operation.

Perform the important checks in this newsletter before inserting the maintenance cartridge to avoid any damage caused by those parts.

Checks to be performed

Please perform the following checks in the new Maintenance Cartridge before installing in printer

1. Push the web wipe flag to ensure it is correctly seated.



2. Verify that the ink collection unit is fully inserted into the maintenance cartridge



